



2141 ICON Way, Vacaville, CA 95688 - Tel: 707.564.4000 – www.iconaircraft.com

# SERVICE BULLETIN

## SB-060716 REV A

**DATE ISSUED:** 6/7/2016  
**DATE EFFECTIVE:** 6/7/2016  
**SUPERSEDES NOTICE:** None  
**SUBJECT:** EXCHANGE OF STATOR ASSY. OF ROTAX ENGINE TYPE 912 i (SERIES)  
**AIRCRAFT AFFECTED:** **MODEL:** A5  
**S/N:** 00001, 00003, 00004, 00005, 00006, 00007, 00008, 00009, 00010, 00011, 00012  
**REQUIRED ACTION:** COMPLY WITH ROTAX SERVICE BULLETIN SB-912 i-006 dated May 26, 2016  
**TIME OF COMPLIANCE:** PER ROTAX SERVICE BULLETIN SB-912 i-006 dated May 26, 2016

**PURPOSE:**

ROTAX has released Service Bulletin SB-912 i-006 dated May 26, 2016 to replace the stator assembly in the ROTAX engine type 912 i(Series). This purpose of this Service Bulletin is to apply the ROTAX Service Bulletin to the ICON A5 Aircraft with effectivities as noted above.

**WARRANTY:**

N/A

**PARTS LIST:**

PART	DESCRIPTION	A5
(Refer to SB-912 i-006)		

**INSTRUCTIONS:**

Please refer to the attached ROTAX Service Bulletin SB-912 i-006 dated May 26, 2016.

**MAKE THE FOLLOWING ENGINE LOGBOOK ENTRY:**

“Service Bulletin SB-060716 and SB-912 i-006 has been complied with and reported to ICON Aircraft Owner Support”.

If you are no longer in possession of this aircraft, please forward this information to the present owner/operator and notify ICON Aircraft, Owners Center at:

ICON Aircraft  
2141 ICON Way  
Vacaville, CA 95688  
(855) FLY-ICON or (707) 564-4000  
[ownersupport@iconaircraft.com](mailto:ownersupport@iconaircraft.com)

Please include the aircraft registration number, serial number, your name, and if known the contact information of the new owner/operator.